

Release Notes for DrayTek Vigor 3912 (UK/Ireland)

Firmware Version	4.4.5.1 – Mainline branch (Formal Release)
Release Type	Critical – Upgrade recommended immediately
Build Date	6 th August 2025
Release Date	11 th September 2025
Revision	5232_8190_6a81e90581
Applicable Models	Vigor 3912, Vigor 3912S
Locale	UK & Ireland Only

Mainline and Release Candidate Firmware Branches:

Mainline - Formal releases of firmware incorporating any bug fixes and firmware improvements.

Release Candidate - Incorporates new features, bug fixes and firmware improvements.

To change firmware from one branch to another as a precaution take a configuration backup before performing the firmware upgrade.

Stable - 4.4.3.6 - Latest release

Mainline - 4.4.5.1 – Adds VRRP TR-069 parameters, and improves WUI security, features and system stability

Important Note: Since 4.4.3.2 firmware version there is support for admin password hashing.

Please note that if you upgrade to this version and later downgrade to a previous version, the admin password will reset to the default, and you will need to reconfigure it. Other settings will not be affected.

New Features

(None)

Improvements

1. Improvements to the WUI security
2. Memory allocation adjustments that improve the high memory usage for Max Connection number of 150K
3. Improvements to the system stability linked with IPv6 WAN2 port and DPDK Anti-DoS support
4. The router will send the DPD request again before announcing the DPD timeout of the VPN connection
5. A note added on the [VPN and Remote Access] > [PPP General Setup] page to explain that Vigor only offers LAN1 IP to OpenVPN clients with AD/LDAP authentication
6. DNS forwarding could not work over VPN
7. Some Vigor routers (e.g., Vigor 2925) could not connect to Vigor 2962/3910/3912 via SSL VPN
8. Fix to a potential error in "L2TP VPN" where the interface was too large to be stored in an unsigned character
9. Fix to typos in the word "XAauth" in [VPN and Remote Access] > [PPP General Setup], and the word "Prase error" in Syslog

10. Allow the Port Redirection/Open Ports/Firewall via Source IP using Domain Name
 11. Improvements to the Internet access stability with enhanced DPDK Anti-DoS mechanisms, including bypassing ICMP packets, automatically adding DNS server IPs to the whitelist, and supporting the whitelists configured on the Firewall DDoS Setup page
 12. App Enforcement did not block QUIC because of outdated signatures
 13. The Brute Force Protection view list in the Dashboard showed a blocked IP count, but the BFP table appeared empty
 14. Decrypt the QUIC initial packets successfully
 15. Support for VRRP TR-069 parameters and for multiple IPv4 VRRP groups
 16. Improvements to the "Firmware Download Link" in the [System Maintenance] > [Firmware Upgrade] page.
 17. Fixed an issue where a wrong IP was displayed in [ACS] > [Network tree] > [Device status]
 18. The displayed VRRP role status of Master and Backup was incorrect
 19. Resolved an issue where XML configurations involving NAT port redirection and open port settings did not take effect until they were reapplied through the router's user interface
 20. Fixed an issue with incorrect GeoIP country classification
 21. Updated menu label from [Applications] > [High Availability] to [Applications] > [High Availability / VRRP]
 22. Updated wording from 'EasyVPN / SSL Setup' to 'EasyVPN / SSL VPN Setup' in [VPN and Remote Access]
 23. Added support for specifying an IP alias in Ping Detection [WAN] > [Internet Access] > WAN Connection Detection
 24. Corrected an issue where an incorrect value was assigned to DH Group 1 in [VPN and Remote Access] > [LAN to LAN]
 25. Corrected an issue where Rx throughput was significantly lower than Tx throughput
 26. Fixed an issue where the 'Disable Ping from the Internet' setting was not functioning
 27. Corrected an issue where ping packets were unexpectedly dropped
 28. Fixed an issue where NAT loopback and open port functionality did not work for IP Alias WAN with TCP traffic
 29. The unexpected syslog errors were issued that were related to "REP Conflict WARN: a=0 p=6 t=2" and showed info about Pseudo Port conflict caused by "srv nat pseudoctl function 4"
 30. Fixed an issue where VPN connections via EasyVPN failed when an ACL was configured in [System Maintenance] > [Management]
 31. Fixed an issue where TR-069 did not work properly when STUN server was configured with an IP address
 32. Corrected an issue with the NetFlow interface index reported via SNMP
 33. Corrected an issue with an error encountered in the Firewall with User-Based
 34. Corrected an issue with failure to block the Alpmix remote control application
 35. Fixed a DHCPv6 buffer leak issue
 36. Corrected an issue where the dashboard became unresponsive due to a high number of BFP entries
 37. Resolved a compatibility issue in which the Vigor router's APM module failed to recognize or manage the AP1062C access point
-

Firmware File Types


The file name of the firmware controls which upgrade type is performed.

If the file name is unchanged (e.g. xxxx.sfw) then the upgrade will just upgrade the firmware, whereas renaming the firmware to a .rst extension will wipe all settings back to factory defaults when upgrading the firmware.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the router's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the router's system maintenance menu and select the correct file. Ensure that you select the SFW file unless you want to wipe out your router's settings back to factory default.



Manual Upgrade

If you cannot access the router's menu, you can put the router into 'TFTP' mode by holding the RESET whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier and recommended – this manual mode is only needed if the web interface is inaccessible.

Firmware Version	4.4.5 – Mainline branch (Formal Release)
Release Type	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Build Date	25 th June 2025
Release Date	25 th July 2025
Revision	5161_8043_7cfc57ae90
Applicable Models	Vigor 3912, Vigor 3912S
Locale	UK & Ireland Only

New Features

1. Support for DrayOS 5 wireless APs
2. Support for XMPP
3. Support for VRRP
4. Support for EasyVPN
5. Support for VPN with Port Knocking
6. Enhance smart actions by enabling multiple actions per profile and saving notifications for configurations

Improvements

System Stability:

1. In some cases, the Web GUI and TR-069 configuration cause the router to reboot
2. A backup task initiated by VigorACS could cause the router to reboot
3. Improvements to the router's system where the device could stop responding every 5 or more days
4. Establishing a third VPN (IKEv2 EAP) connection could trigger a reboot
5. The CPE stayed in boot loop after VigorACS based firmware upgrade if the system parameter 15 (isRebootAfterDownload) was enabled
6. Improvements to the system stability that could be affected by SMS/SSL VPN functionality
7. If a password containing "%" character was entered in External Devices, it could cause a device reboot

VPN:

8. The VPN 2FA email content has been updated
9. Rename of "EasyVPN/SSL" with "EasyVPN / SSL VPN"
10. All traffic (0.0.0.0/0) through VPN can be routed now
11. Improvements related to DPDK Anti_DoS that affected OpenVPN performance
12. Fix the routing issues occurred in an MPLS via a VPN connection
13. Improvements to the EasyVPN connection/HTTPS server responding issues occurring when accessed by a domain name
14. In some circumstances VPN tunnels could drop and did not re-establish because the VPN info was not released properly
15. Fix for the issue where VPN LAN to LAN with Translate Local Network "Translate Specific IP" always used x.x.x.0 for Local Network

16. A VPN connection could not be established if the VPN server used UBDDNS and the DNS server responded with TTL=0

Security / TOTP / Port knocking

17. Enhanced security by removing weak ciphers from the SSH server
18. An option added to require both Access List and Port Knocking for router access
19. In some circumstances the Firewall filter by MAC Address failed to work
20. Add an IP to block list in the DoS Flood table did not work
21. The IP of a more remote subnet configured in VPN LAN to LAN profile could scan the routers service port (while the service was disabled)
22. Fix the issue linked to LAN Access Control with IP Object Range Type that could not block VPN from accessing the router's Management interface
23. Improvements to the firewall where rule supposed to block all WAN traffic to the router, however after 5 minutes, the logs indicated that the traffic was still passing through

Miscellaneous:

24. Improvements to the DPDK SP flush
25. The Link Aggregation status can be displayed in the Dashboard
26. A quick link for the BFP Block IP List added on the Dashboard
27. Support to display the detailed information for Port Statistics
28. New service providers added: "SerwerSMS.pl" and "www.voipvioce.it(IT)"
29. An error message /warning message will be printed in Syslog when SMS quota reaches 0
30. Improvements related to cached DNS for TR-069
31. Further improvements to the RADIUS Request Interval functionality
32. DrayDDNS behind NAT could not be updated
33. The dyn.com DDNS could not update after WAN PPPoE IP address changed
34. The system could not send an SMS using MessageBird nor custom SMS profiles
35. Improvements to configuration of the authentication method for local administrator users
36. APP Enforcement Profile did not block SnapChat and WhatsApp
37. The WANx-first for DrayDDNS service when Internet IP was used did not work as expected
38. The TR-069 CPE notification did not provide the WAN IP address
39. The route policy specific gateway did not work on new connections
40. A CPE did not send Periodic Inform when ACS kept requesting Connection Requests
41. The TR-069 URL could not be removed when deleting the CPE with the option "Clear TR-069 URL" enabled on the ACS
42. An SMS could not be sent when recipient's number was set with "+" sign and configured in Custom SMS Service Object
43. Virtual WAN could not establish PPPoE when both physical WAN and virtual WAN used the same VLAN tag or were untagged

Known Issues

(None)

Firmware Version	4.4.3.5 (Formal Release)
Release Type	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Build Date	2 nd June 2025
Release Date	18 th July 2025
Revision	4961_7654_518e8b3a94
Applicable Models	Vigor 3912, Vigor 3912S
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. The router could become unresponsive when both WCF and DNS Filters were enabled during unstable Internet connections
2. The router could become unresponsive every few days due to the anti-DoS queue being full
3. The router could stop responding when a broken Web login 2FA configuration was used in the previous firmware. It is necessary to regenerate the 2FA settings after upgrading to the new firmware`
4. Improvements to the mechanisms linked with Slab Panic / SOCK_DYNA_BUF errors
5. The Web UI was affected when the IP Group name under [Object Setting] > [IP Group] contained a comma
6. Web GUI and router stability improvements
7. Improvements to the wording; “null” is replaced with “empty”
8. Fix for the manual time zone configuration for Athens
9. Fix for the missing Chinese interface after firmware update
10. The tab formatting was missing in some CLI help menu items
11. An IP could not be added to the DoS Flood block list
12. A single quote in the IP Group name could break the QoS page
13. An issue where "Unknown WAN" was displayed in the VigorACS server
14. A compatibility issue between the SMS Service Object and BulkSMS.com
15. An issue where the Vigor 3912 Web UI was not reachable via virtual WAN IP
16. Fix for the Virtual WAN PPPoE dial-up failure when a VLAN tag overlapped with physical WAN
17. Compatibility improvements with the Remote Dial-In VPN backup configuration that can be now restored from Vigor 2927 to Vigor 3912
18. Fix an issue with random firmware upgrade failures occurred via VigorACS when an "Always On" OpenVPN tunnel existed
19. LAN Access improvements related to IP Object - Range Type that could not block VPN from accessing the router's management interface
20. Automatically deleted the “cpu_busy.tar” file during debug log generation if it was over one month old, to speed up log downloads
21. Fix the issue where the router no longer attempted to establish a VPN connection if the DNS server responded to the VPN Server's domain name with TTL=0

Known Issues

1. At present, DrayOS5 APs are not supported by Vigor 3912

Firmware Version	4.4.3.4 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	27 th March 2025
Release Date	14 th May 2025
Revision	4926_7605_b8950f82bc
Applicable Models	Vigor 3912, Vigor 3912S
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. Improvements to the wording; “null” is replaced with “empty”
2. Support for TCP protocol for Port Knocking
3. Improvements to the update method for User Management’s data quota
4. BFP (Brute Force Protection) Status added to the Dashboard
5. The CMS profiles that are not enabled on the Main Filter page are hidden
6. The “Product Registration” is renamed to “Registration & Services”
7. New SMS Service Providers added: “sms.mitake.com.tw” and “SerwerSMS.pl”
8. A new TR-069 parameter added for [Applications] > [Radius/TACACS+] > [Certificate]
9. A note added to explain the ‘None’ item for Protocol on the [NAT] > [Port Knocking] page
10. The “Malloc OSPF config fail” error log has been removed when OSPF is enabled but no profiles are configured
11. The Router Policy Name (comment) is displayed in the dropdown menu instead of displaying the “Index number”
12. A prompt added to re-enter the verification code when changing other settings on the [NAT] > [Port Knocking] page
13. The username length increased in [User Management] and [USB] > [User Management] sections to 32 characters (previous limit was set to 11 characters)
14. Enhance of the DPDK Anti-DoS mechanism to reduce high CPU usage caused by UDP broadcast/multicast floods that could lead to instability of the router
15. Fix for the STUN server related issues
16. Buffer management improvements related to SSL VPN service
17. The router could become unresponsive after enabling login with 2FA
18. The all traffic (0.0.0.0/0) through VPN improvements
19. Some of the IGMP Status information was incorrect
20. The WAN IP object/group wasn’t listed in firewall source IP
21. Improvements related to the high CPU usage caused by UDP broadcast/multicast flood
22. Fix for the connection issues related to the IPsec X.509 H2L VPN
23. Fix for sending SMS via MessageBird or custom settings
24. RADIUS Request Interval improvements
25. High Availability Hot-Standby Config Sync was not functioning correctly
26. Improvements to the WANx prioritization for DrayDDNS when using Internet IP
27. Improvements with the log for updating an external device turned into garbled text
28. The Syslog client failed to work when using the WAN Alias IP

29. Improvements to the DoS attack mechanism that could cause high CPU usage and make the router unresponsive
30. Fix an issue where creation of a Let's Encrypt certificate with No-IP domain did not work
31. The router could become unresponsive while establishing the 3rd IKEv2 EAP VPN connection
32. Improvements to the online status showing "Fiber" even when the Ethernet connection was selected
33. The correct icon is displayed for VigorAP 918R, VigorAP 805, and VigorAP 962C via APM
34. Fix for the firewall block issue where a rule was set with WAN->Localhost direction and was ignored by the system after 5 minutes
35. Fix for the issue where router could become unresponsive when logging into the WUI with TOTP after downgrading from 4.4.3.2 to 4.4.3.1
36. Improvements to the WAN RX Packet Count that displayed negative values when using the CLI command "show state"
37. Fix an issue where the Gateway setting appeared if WAN/LAN was selected for the Failover to option on [Routing] > [Route Policy]
38. Improvements to the router stability related to dray_dpdk, QEMU and configuration backup job via VigorACS server
39. Fix for the issue where Internal Syslog Server continued to receive Syslog from the WAN, even after the NAT Open Port rule was disabled
40. The IKEv2 VPN was disconnecting when a Peer Domain Name was specified and receiving DNS server responses with a TTL of 0
41. When using the packet capture function on the web interface, P1 was incorrectly set to enabled even after stopping the packet capture function

Known Issues

(None)

Firmware Version	4.4.3.2 (Formal Release)
Release Type	Critical – Upgrade recommended immediately
Build Date	28 th November 2024
Release Date	24 th December 2024
Revision	4859_7498_8085331
Applicable Models	Vigor 3912, Vigor 3912S
Locale	UK & Ireland Only

New Features

1. Support to enable/disable Port 1 to Port 12 via CLI:
port setting -p [port number] -e [0 for disable; 1 for enable]
For example, port 11 can be disabled with the following command:
port setting -p 11 -e 0
2. Support for TLS 1.3 added to [System Maintenance] > [Management]
3. Support for checking the SSD/eMMC health information on [Linux Applications] > [Storage], and via CLI command:
linux dstatus -s
4. The new tabs for Custom Rules and Rule Exclusion List options added on [Linux Applications] > [Suricata]
5. TOTP 2-factor authentication (Google Authenticator) is now available for authenticating web interface administrator access from the Internet
[System Maintenance] > [Administrator Password]

Improvements

1. Web GUI Security improvements
2. The GeoIP database updated to version 2024-10-01
3. The [Diagnostics] > [Debug log] feature enhancements
4. Support added for responding to ARP Probe packets
5. Improvements to the view sort arrows on the [Firewall] > [Defense Setup] page
6. The syslog output changed to "SMS/Email alert suppressed" when triggered by Notification Object for VPN Tunnel with "Downtime Limit" settings enabled
7. The new pop-up notification added:
"If you have enabled DNS Filter on CSM Profile>>DNS Filter and want to access Vigor router via a specified domain name, type the domain name in [Domain name allowed] on [System Maintenance>>Management>>LAN Access Setup]"
8. The redundant "Clear All" button has been removed from [Applications] > [Dynamic DNS]
9. The "optional" note added for [Objects Setting] > [IP Object] for MAC Address selection
10. A note related to EOL AP-900 was removed in [Central Management] > [AP] > [Load Balance]
11. IPv6 status will be shown in green only when IPv6 interface is enabled
[LAN] > [General Setup]
12. Individual clear buttons added for Restore Backup Firmware/Config on [System Maintenance] > [Configuration Export]
13. BGP over GRE did not work
14. The correct AP906 icon can be displayed in APM
15. Fix for the high packet loss with Starlink connections

16. Improvements to system stability and compatibility with IPTV connections
17. Fix an issue where a wrong port triggering was linked with the defined Smart Action profile
18. Improvements to the IP phones SIP registration being lost when used over VPN LAN to LAN connections
19. Router's stability improvements linked with QEMU system
20. Block list not showing when IP is blocked via Data Flow Monitor
21. Fix an issue with the internet access that could be caused by Fast NAT using incorrect MSS values
22. The [Diagnostics] > [NAT Sessions Table] WUI page did not display all the data
23. Failed to restore V3912S > NAT > Port Redirection/Open Ports .bak file
24. The VPN Traffic Graph H2L traffic accuracy improvements
25. Changing LAN1 IP Address could cause inaccessibility after reboot (ports 9–12 only)
26. VPN Matcher special characters [] () compatibility improvements
27. The client data quota could not be recorded if the router was power cycled
28. The URL Filter did not block HTTPS websites when TLS 1.3 hybridized Kyber was enabled in the browser
29. Vigor 3912S model only: VigorConnect and Suricata did not start after resetting to their default configurations
30. OpenVPN certificate compatibility improvements
31. The system would show two temperature sensor icons when only one sensor was connected [Online Status] > [Physical Connection]

Known Issues

(None)

Firmware Version	4.3.6.2 (Formal Release)
Release Type	Critical – Upgrade recommended immediately
Build Date	29 th October 2024
Release Date	26 th November 2024
Revision	4306_5107_ed63ed3
Applicable Models	Vigor 3912, Vigor 3912S
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. Web GUI Security improvements (CVE-2024-46550, CVE-2024-46568, CVE-2024-46571, CVE-2024-46580, CVE-2024-46586, and CVE-2024-46588 ~ CVE-2024-46598)
2. Resolved an issue with DMZ host set for WAN3 Alias IP when P1/P2 port is changed to the LAN port mode

Known Issues

(None)

Firmware Version	4.3.6.1 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	23 rd July 2024
Release Date	13 th August 2024
Revision	4188_5045_109e0bd
Applicable Models	Vigor 3912, Vigor 3912S
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. Web GUI Security improvements
2. Description modified for the Fast NAT check box on NAT>>Fast Routing/NAT.
3. Resolved an issue with failure to use the new created Google API via Hotspot.
4. Resolved an issue with HA slave when WCF enabled was enabled
5. Resolved an issue with the lack of the WAN interface setting field on VPN>>VPN Matcher Setup.
6. Resolved an issue with the hotspot HTTPS redirection error by the HTTPS management port being set as non-default.
7. Resolved an issue with the URL filter failed to block HTTPS websites when TLS 1.3 hybridized Kyber was enabled in the web browser and web server used the cipher
8. Resolved an issue with the WUI of Objects Setting>>SMS/Mail Service Object lost connection temporarily after clicking "Send a Test Message"
9. Resolved an issue that the IPsec Peer Identity profile still appeared and was selected on the remote dial-in profile, even if it was deleted or renamed.

Known Issues

(None)

Firmware Version	4.3.6 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	7 th June 2024
Release Date	2 nd August 2024
Revision	4091_4929_2bc9d11
Applicable Models	Vigor 3912, Vigor 3912S
Locale	UK & Ireland Only

New Features

1. Support for Vigor 3912S
2. The 'Telegram' and 'Block IP' smart actions added to the [Application] > [Smart Action] page

Improvements

1. VigorConnect can be enabled from the router's WUI in [Linux Applications] > [VigorConnect]
2. Password mechanism changed to force admin to change the password from the default password
3. In some circumstances BGP routing didn't work
4. Support for detailed Port Statistics added in [Diagnostics] > [Port Statistics]
5. Improvements to the DoS defense alerts accuracy
6. Improvements to the VPN mechanism (L2TP over IPsec)
7. The note to copy 2FA token has been added for the VPN Dial-in User WUI profile pages
8. The Port Physical Type selection did not match the [Port Setup] and [WAN] > [General Setup] pages
9. The Port Knocking for Local Service field added to [System Maintenance] > [Management]
10. The display mechanism for [System Maintenance] > [Management] WUI for "Port Knocking for Local Service" and "Brute Force Protection" will show additional option in the same manner
11. The note in [System Maintenance] > [Firmware Upgrade] matches the new firmware file type (".sfw" instead of ".all")
12. The new note added to the [VPN and Remote Access] > [PPP General Setup] page:
"4. AD/LDAP Authentication only supports PPTP / L2TP / SSL / OpenVPN / IPsec XAuth and doesn't support IKEv2 EAP"
13. Simplified time format, and log sorting set from the latest to the oldest (like in Syslog Explorer) will be used by [Linux Applications] > [Log collector] page
14. The Port Knocking Tools download link added on the [NAT] > [Port Knocking] page
15. Redesign of the [System Maintenance] > [Configuration Export] "Restore Backup Firmware / Config", and [NAT] > [Fast Routing/NAT] pages
16. Fix for the DoS Defense alerts linked with the DHCP packets
17. Fix for the DrayDDNS WAN IP updates
18. User data quota in User Management didn't work
19. Fix for the auto timezone option that could not pick the right zone
20. In some circumstances the DHCP Server could not assign over 1000 IP addresses
21. Fix for the NAT Open Port, Port Redirection, and Port Knocking WAN selection where unavailable WAN interfaces were also selectable in the WUI
22. The router could stop responding every few hours after enabling the WCF

23. The first IP/LAN IP in Smart Action did not work
24. The router couldn't send SMS when VPN and TOTP were used
25. Login from a VPN subnet or non-directly connected LAN could fail
26. The get code page showed incorrect model of the router (3910) when the advanced authentication web login from wan was enabled
27. The Log collector did not work after upgrading to a beta firmware
28. The router could stop responding when the conntrack (connection tracking) table is full
29. Fix for the VPN settings inconsistency when accessed via WUI and CLI
30. Hotspot Web Portal - Social login with Google account didn't work
31. In some cases Windows L2TP IPsec VPN could disconnect every 8 hours.
32. When a sudden power off occurred, the router could boot up by using the backup image
33. When turning the Smart Action profile on or off, router could stop responding
34. Improvements to the VPN mechanism (L2TP over IPsec)
35. Improvements to the LAN to LAN Dial-out profiles set with the domain name using uppercase letters (did not work)
36. The router could not detect the USB temperature sensor (TEMPer1F_V3.4) after a normal reboot and power off/on
37. Fix for the issue where router did not boot up on a cold reboot when SFP-10G-T100 was connected to SFP1 interface
38. The UDP session over WireGuard VPN wasn't released after the VPN reconnection
39. Fix for the Advanced Authentication options for Web Login that could disappear after importing a configuration file from Vigor 3910
40. VoIP - Incoming/outgoing calls failed based on "Allow pass inbound fragmented large packets" status
41. In some circumstances, testing ping could cause DNS failure and WAN Offline (WAN Connection Detection failure) issues. Brute Force Protection will exclude some of the well known DNS IP addresses
42. Improvements to the URL reputation mechanism that did not block some specific websites and print the "Get Request Resource Failure" in the syslog
43. Fix for the ping failure issue from LAN P9-P10 (related to the Link Aggregation setting that wasn't cleared completely)

Known Issues

(None)

Firmware Version	4.3.5.2 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	30 th April 2024
Release Date	11 th June 2024
Revision	3733_4582_c35e39d
Applicable Models	Vigor 3912
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. The network connection stability improvements
2. Improvements to the network security related to the password and DHCP functionality
3. Password mechanism changed to force admin to change the password from the default password
4. Fix for the IPv6 firewall functionality
5. Fix for the IKEv2 EAP with the iOS VPN client issue
6. The Configuration Backup button in the top section of the GUI did not work

Known Issues

(None)

Firmware Version	4.3.5.1 (Initial Release Firmware)
Release Type	Initial Release
Build Date	8 th January 2024
Release Date	8 th February 2024
Revision	3694_4567_1a05379251
Applicable Models	Vigor 3912
Locale	UK & Ireland Only

First Firmware Release for this model

New Features

(None)

Improvements

(None)

Known Issues

(None)

[END OF FILE]