Release Notes for DrayTek VigorAP 805 (UK/Ireland)

Firmware Version	5.0.6 (Formal Release)
Release Type	**Regular** – Upgrade recommended when convenient
Build Date	12th August 2025
Release Date	23rd July 2025
Web Version	r4228.b62a3736
Core Version	r669
Applicable Models	VigorAP 805
Locale	UK Only

New Features

(None)

Improvements

1. Multiple SSID schedule profiles can now be used in [Configuration] > [Wireless LAN] > [Radio Settings]
2. The network connection status can be shown in [System Maintenance] > [Management] > [XMPP]
3. Improvements to the management VLAN that could be set back to default when using config sync in AP management

Known Issues

(None)

Firmware File Types

The file name of the firmware controls which upgrade type is performed.
If the file name is unchanged (e.g. *xxxx*.**sfw**) then the upgrade will just upgrade the firmware, whereas renaming the firmware to a .**rst** extension will wipe all settings back to factory defaults when upgrading the firmware.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the AP's system maintenance menu.

To upgrade firmware, select *'Firmware'* from the AP's system maintenance menu and select the correct file. The access point will perform the upgrade and may automatically reboot once this completes.

Manual Upgrade

If you cannot access the AP's menu, you can put the AP into 'TFTP' mode by holding the FACTORY RESET button whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by LED flashing. This mode will also be automatically enabled by the access point if there is a firmware/settings abnormality. Upgrading from the web interface is easier.

Firmware Version	5.0.5 (Formal Release)
Release Type	**Critical** – Upgrade recommended immediately
Build Date	14th April 2025
Release Date	24th April 2025
Web Version	r4135.2862fb02
Core Version	r656
Applicable Models	VigorAP 805
Locale	UK Only

New Features

(None)

Improvements

1. WLAN driver updates with security improvements (CVE-2025-20631, CVE-2025-20632 and CVE-2025-20633)
2. The 'Default VLAN' is added to [Configuration] > [LAN] > [VLAN List]
3. The [Configuration] > [LAN] > [Interface VLAN] section added for port VLAN configuration
4. The [System Maintenance] > [Management] > [XMPP] section added for XMPP protocol
5. SSH server security improvements (proxy-related functions has been disabled)

Known Issues

(None)

Firmware Version	5.0.3 (Formal Release)
Release Type	**Initial Release**
Build Date	2nd December 2024
Release Date	28th January 2025
Web Version	r4047.59bc8092
Core Version	r640
Applicable Models	VigorAP 805
Locale	UK Only

First Firmware Release for this model

[END OF FILE]