

## **Release Notes for DrayTek VigorSwitch G2282x (UK/Ireland)**

Firmware Version	2.10.2 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	22 <sup>nd</sup> August 2025
Release Date	3 <sup>rd</sup> October 2025
Build Revision	41baf69
Applicable Models	VigorSwitch G2282x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Improvements to the stacking feature
2. Stacking mode can also support LAG ports in Static MAC, VLAN, GVRP, Multicast, STP, QoS, ONVIF Surveillance, IP Source Guard, Port Security, Dynamic ARP Inspection, DHCP Snooping, IP Conflict Prevention, Loop Protection, and Port Recovery

### **Known Issues**

(none)

---

Firmware Version	2.10.1 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	10 <sup>th</sup> April 2025
Release Date	22 <sup>nd</sup> May 2025
Build Revision	b312861
Applicable Models	VigorSwitch G2282x
Locale	UK & Ireland Only

### **New Features**

1. Support for up to four devices for Physical Stacking

### **Improvements**

1. Optimising the Physical Stacking mechanism

### **Known Issues**

(none)

Firmware Version	2.9.7 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	14 <sup>th</sup> March 2025
Release Date	9 <sup>th</sup> May 2025
Build Revision	59996db
Applicable Models	VigorSwitch G2282x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Improvements to the Web GUI security
2. Improvements to the DNS domain registration with TR-069 service

### **Known Issues**

(none)

Firmware Version	2.9.5 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	15 <sup>th</sup> July 2024
Release Date	18 <sup>th</sup> November 2024
Build Revision	ef29dcb
Applicable Models	VigorSwitch G2282x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Improvements to the TR-069 parameter related issues
2. The CPU usage mechanism improvements
3. Fix an issue related to the IP Source Guard and DHCP snooping used simultaneously

### **Known Issues**

(none)

Firmware Version	2.9.4 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	19 <sup>th</sup> April 2024
Release Date	31 <sup>st</sup> October 2024
Build Revision	24df0f6
Applicable Models	VigorSwitch G2282x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Password mechanism changed to force admin to change the password from the default password
2. The ICP table size increased to 1024
3. Port Description added on the Bandwidth Utilization page
4. The configuration process for LAG has been updated
5. The firmware release notifications mechanism added
6. The syslog display time adjustments related to the daylight-saving time
7. The SFP+ port information can be displayed on the dashboard
8. The management port configuration option improvements
9. The device MAC address details included in syslog

### **Known Issues**

(none)

Firmware Version	2.9.1 (Formal Release)
Release Type	<b>First Firmware Release</b>
Build Date	10 <sup>th</sup> July 2023
Release Date	13 <sup>th</sup> March 2024
Build Revision	r3a6d25b
Applicable Models	VigorSwitch G2282x
Locale	UK & Ireland Only

## First Firmware Release

[END OF FILE]