

## **Release Notes for DrayTek VigorSwitch P1282 (UK/Ireland)**

Firmware Version	2.9.8 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	6 <sup>th</sup> June 2025
Release Date	30 <sup>th</sup> June 2025
Build Revision	a79e36f
Loader Version	3.5.3
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. HTTPS related web performance improvements
2. Fix the issue where certain PoE devices could not be powered when using IEEE 802.3bt
3. CPE information could not be accessed due to TR-069 settings related to VigorACS
4. Improvements to the QoS inaccurate readings linked with egress and ingress speeds exceed 1Gbps

### **Known Issues**

1. Users can't downgrade the firmware below 2.8.x, if the loader version is 3.5.2  
To check the loader version, open the Dashboard page or use this CLI command:  
*show info*
-

Firmware Version	2.9.7 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	14 <sup>th</sup> March 2025
Release Date	9 <sup>th</sup> May 2025
Build Revision	59996db
Loader Version	3.5.3
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Improvements to the Web GUI security
2. Improvements to the DNS domain registration with TR-069 service

### **Known Issues**

1. Users can't downgrade the firmware below 2.8.x, if the loader version is 3.5.2  
To check the loader version, open the Dashboard page or use this CLI command:  
*show info*

Firmware Version	2.9.5 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	15 <sup>th</sup> July 2024
Release Date	23 <sup>rd</sup> October 2024
Build Revision	ef29dcb
Loader Version	3.5.3
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Improvements to the TR-069 parameter related issues
2. The CPU usage mechanism improvements

### **Known Issues**

1. Users can't downgrade the firmware below 2.8.x, if the loader version is 3.5.2  
To check the loader version, open the Dashboard page or use this CLI command:  
*show info*

Firmware Version	2.8.5 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	11 <sup>th</sup> April 2023
Release Date	12 <sup>th</sup> May 2023
Build Revision	c26610f
Loader Version	3.5.3
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Fixed an issue where Syslog could use the wrong timestamp

### **Known Issues**

1. Users can't downgrade the firmware below 2.8.x, if the loader version is 3.5.2  
To check the loader version, open the Dashboard page or use this CLI command:  
*show info*

Firmware Version	2.8.3 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	10 <sup>th</sup> January 2023
Release Date	21 <sup>st</sup> March 2023
Build Revision	a452dac
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Further improvements to the Web GUI
2. The PoE chip driver upgrade
3. [System Maintenance] > [General] > [Firmware] page can now display the latest firmware version available online
4. Improvements to the renew certificate mechanism

Firmware Version	2.8.0 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	13 <sup>th</sup> May 2022
Release Date	10 <sup>th</sup> August 2022
Build Revision	c286e45
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

### **New Features**

1. Support the new PoE chip driver

### **Improvements**

1. Improved Web GUI Security
2. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
3. The HTTPS management port can be edited
4. Number of entries for the ICP (IP Conflict Prevention) and ICD (IP Conflict Detection) table has been increased to 1024

Firmware Version	2.6.7 (Formal Release)
Release Type	<b>First Firmware Release</b>
Build Date	15 <sup>th</sup> October 2021
Release Date	16 <sup>th</sup> February 2022
Build Revision	95993d5
Applicable Models	VigorSwitch P1282
Locale	UK & Ireland Only

#### **First Firmware Release**

**[END OF FILE]**