

## **Release Notes for DrayTek VigorSwitch P2540x (UK/Ireland)**

Firmware Version	2.9.4 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	29 <sup>th</sup> April 2024
Release Date	4 <sup>th</sup> November 2024
Build Revision	24df0f6
Applicable Models	VigorSwitch P2540x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Password mechanism changed to force admin to change the password from the default password
2. The ICP table size increased to 1024
3. Port Description added on the Bandwidth Utilization page
4. The configuration process for LAG has been updated
5. The firmware release notifications mechanism added
6. The syslog display time adjustments related to the daylight-saving time
7. The SFP+ port information can be displayed on the dashboard
8. The management port configuration option improvements
9. The device MAC address details included in syslog

### **Known Issues**

(none)

---

Firmware Version	2.7.4 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	07 <sup>th</sup> July 2022
Release Date	05 <sup>th</sup> August 2022
Build Revision	023db45
Applicable Models	VigorSwitch P2540x
Locale	UK & Ireland Only

### **New Features**

1. The function of Dying gasp added allowing the switch to indicate the power-related downtime
2. Added the new algorithm (IP only or Source Port only) for LAG
3. Support for 10Gigabit Ethernet port auto linkup added

### **Improvements**

1. 10G ports set with link aggregation did not working after device reboot
2. Updated HTTPS mechanism to address the CVE-2022-0778 (OpenSSL)
3. The fibre ports media type default setting is set to Auto
4. Port Bandwidth Utilization page's colours match the Dashboard
5. The RADIUS settings disappeared after restarting the switch
6. The status information of the SFP optical module improvements
7. The VLAN interface uplink TPID setting could not be stored by the switch

Firmware Version	2.6.7 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	26 <sup>th</sup> January 2021
Release Date	25 <sup>th</sup> August 2021
Build Revision	1959
Applicable Models	VigorSwitch P2540x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Updated MyVigor authentication method

Firmware Version	2.6.4 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	8 <sup>th</sup> August 2020
Release Date	7 <sup>th</sup> September 2020
Build Revision	1916
Applicable Models	VigorSwitch P2540x
Locale	UK & Ireland Only

### **New Features**

1. DHCP Relay is now available in the [Switch LAN] > [DHCP Server / Relay] menu.

### **Improvements**

(none)

Firmware Version	2.6.3 (Formal Release)
Release Type	<b>First Firmware Release</b>
Build Date	29 <sup>th</sup> June 2020
Release Date	6 <sup>th</sup> August 2020
Build Revision	1889
Applicable Models	VigorSwitch P2540x
Locale	UK & Ireland Only

## First Firmware Release

[END OF FILE]