

Release Notes for DrayTek VigorSwitch P2540xs (UK/Ireland)

Firmware Version	3.9.7 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	6 th March 2025
Release Date	9 th May 2025
Build Revision	489852f
Loader Version	3.5.1
Applicable Models	VigorSwitch P2540xs
Locale	UK & Ireland Only

New Features

(none)

Improvements

1. Improvements to the Web GUI security
2. Improvements to the DNS domain registration with TR-069 service

Known Issues

1. Users can't downgrade the firmware below 2.7.x, if the loader version is 3.5.1
To check the loader version, open the Dashboard page or use this CLI command:
show info
-

Firmware Version	3.9.5 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	15 th July 2024
Release Date	21 st November 2024
Build Revision	ef29dcb
Loader Version	3.5.1
Applicable Models	VigorSwitch P2540xs
Locale	UK & Ireland Only

New Features

(none)

Improvements

1. Improvements to the TR-069 parameter related issues
2. The CPU usage mechanism improvements
3. Fix an issue related to the IP Source Guard and DHCP snooping used simultaneously

Known Issues

1. Users can't downgrade the firmware below 2.7.x, if the loader version is 3.5.1
To check the loader version, open the Dashboard page or use this CLI command:
show info

Firmware Version	3.9.4 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	19 th April 2024
Release Date	23 rd October 2024
Build Revision	24df0f6
Applicable Models	VigorSwitch P2540xs
Locale	UK & Ireland Only

New Features

(none)

Improvements

1. Password mechanism changed to force admin to change the password from the default password
2. The ICP table size increased to 1024
3. Port Description added on the Bandwidth Utilization page
4. The configuration process for LAG has been updated
5. The firmware release notifications mechanism added
6. The syslog display time adjustments related to the daylight-saving time
7. The SFP+ port information can be displayed on the dashboard
8. The management port configuration option improvements
9. The device MAC address details included in syslog

Known Issues

1. Users can't downgrade the firmware below 2.7.x, if the loader version is 3.5.1
To check the loader version, open the Dashboard page or use this CLI command:
show info

Firmware Version	3.8.2 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	06 th December 2022
Release Date	23 rd December 2022
Build Revision	d896b83
Applicable Models	VigorSwitch P2540xs
Locale	UK & Ireland Only

New Features

(none)

Improvements

1. Management ports of the switch can now be amended in GUI for HTTP/HTTPS/telnet
2. New PoE chip driver

Firmware Version	3.7.4 (Formal Release)
Release Type	First Firmware Release
Build Date	25 th July 2022
Release Date	12 th September 2022
Build Revision	r023db45
Applicable Models	VigorSwitch P2540xs
Locale	UK & Ireland Only

First Firmware Release

[END OF FILE]